UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,829,553 B2 Page 1 of 1

DATED : December 7, 2004 INVENTOR(S) : Sunil K. Jain et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8,

Line 13, "by with the second output pin" should read -- with the second output pin --. Lines 50-51, "the instruction....determine the second" should read -- the instructions... determine the second --.

Column 9,

Lines 14-15, "the instruction when executed" should read -- the instructions when executed --.

Line 21, "by with the second output" should read -- with the second output --.

Signed and Sealed this

Fourteenth Day of March, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office